

17 8 0069  
1. ~~Is this action?~~  
2. Johnston file ~~copy to Smith~~ 36748

August 22, 1979

Mr. John P. Saad  
John P. Saad and Sons  
3655 Trousdale Drive  
Nashville, Tennessee 37204

Re: Site Inspection - August 20, 1979

Dear Mr. Saad:

This letter is to confirm my visit to your facility on August 20, 1979 with Ruth Yates of the Division of Solid Waste Management. At the time of this inspection we found the following items:

1. The underground tanks making up the oil/water separator system were partially cleaned out. The first two tanks were completely empty, however, the third tank still contained some oil. All three tanks must be completely cleaned out and inspected before they may be put into use. Written approval must be obtained before this system is used.
2. The dikes around the tank area and the loading area are still not complete. There has been no work done on concreting the ground within the dike area.
3. A test dig with a backhoe revealed the existence of sludge below the surface of the ground in the area of the old pond. This material is to be removed and taken to the landfill along with the soil stockpiled nearby. When all digging is complete this office is to be notified and an inspection is to be made to determine if digging has been adequate. Written notice will be given when all work is considered satisfactory.

If there are any questions, please feel free to contact me. Please keep us informed as to the progress of your operation.

Sincerely,

Barry W. Sulkin  
Water Quality Specialist  
Division of Water Quality Control

BWS/dj 3-11

cc: Terry Cothron, WQC  
EPA Emergency Operations Branch, Atlanta  
Lee Breckenridge, Attorney General's Office

